

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-004219**Date Inspected:** 06-Sep-2008**Project Name:** SAS Superstructure**OSM Arrival Time:** 630**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1530**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Ken Zhang**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG Assembly**Summary of Items Observed:**

This report serves to document the events occurring on this date at the following location. Caltrans Quality Assurance (QA) Inspector Robert Vatcher arrived on site at the Zhenhua Port Machinery Company (ZPMC) facility at Changxing Island, in Shanghai, China, for the purpose of monitoring welding and fabrication of the San Francisco / Oakland Bay Bridge (SFOBB) components. The QA Inspector observed the following:

Heavy Bay III

QA observed ZPMC QC personnel performing final visual examination on deck panels;

DP557-001-ZPMC personnel indicated multiple locations requiring weld reinforcement blending by manual grinding. Several ZPMC QC personnel and AB/F QC were involved performing said visual examinations. QA performed a cursory visual examination as well following behind both contractor QC. QA inquired about the weld cap blending and if QC personnel would be following up with another final visual examination. ZPMC QC responded with "yes."

DP563-001

DP572-001

DP596-001

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

DP571-001

North Fabrication Yard

QA was tasked with performing a selection of random locations for radiographic testing (RT) to be performed by ZPMC NDT personnel on transverse complete joint penetration joints for the following Deck panels;

DP119-1-153

DP119-2-153

DP281-1-117

DP092-1-117

DP254-1-189

DP362-1-189

DP470-1-189

Summary of Conversations:

No relevant conversations this date.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Ady Velasco 138-1694-2685, who represents the Office of Structural Materials for your project.

Inspected By:	Vatcher,Robert	Quality Assurance Inspector
Reviewed By:	Cuellar,Robert	QA Reviewer
